

Flexane® Fast Cure Rubber Repair Putty

Description:

A fast-curing, flexible urethane for repairing rubber equipment.

Intended Use:

Industrial Use: Repair worn or damaged rubber equipment; form protective linings in equipment subject to wear, impact, abrasion, vibration, expansion, and contraction.

Features:

Fast cure, Room temp.

Limitations:

Suitability of product is determined by the end user for their application and process.

Typical Physical Properties: Technical data should be considered representative or typical only and should not be used for specification purposes.

220 mg loss per 1,000 revol.

350 volts/mil (13.78 Kv/mm)

Typical Values

98 Shore A

Cured 7 Days @ 75°F (24°C)

Abrasion Resistance
Dielectric Strength
Hardness
Maximum Elongation

Maximum Operating Temperature Percent Solids by Volume

Tear Resistance Tensile Strength 500% Dry: 180°F (82° C); Wet: 120°F (49°C) 100

275 pli (48 N/mm) 2,400 psi (16.5 MPa)

Uncured Properties @ 72°F (23°C)

Color

Coverage (1/4" / 6.35mm)
Cured Shrinkage
Functional Cure

Light Duty Service

Mix Ratio Mixed Viscosity Pot Life Specific Volume Black

94 in2/lb (1337 cm2/kg) 0.0014 in/in (cm/cm)

3 hrs. 2 hrs

> 80 resin:20 curing agent /wt Thixotropic paste 8 min. @ 75°F (24°C) 23.5 in3 /lb (0.849 cm3/g)

Surface Preparation:

For METAL SURFACES, thoroughly clean area to be repaired, rebuilt, or lined with Devcon® Cleaner Blend 300. Remove any oil, grease, or dirt. Roughen surface by grinding with a coarse wheel or an abrasive disc pad. To prime this surface, apply a coat of Devcon FL-10 Primer and allow to dry tack-free for 5-15 minutes. If the metal surface requires maximum tear resistance or is exposed to moisture, or if submerged in water, use Devcon® FL-10 and Devcon® FL-20 Primer.

For RUBBER SURFACES, thoroughly clean area with an abrasive pad and Devcon® Cleaner Blend 300. Surface can also be roughened with a grinding wheel so that it is coarse and free from oil and dirt that may clog the "pores" of the rubber. Wipe or roughen surface with Cleaner Blend 300 until the cloth no longer picks up the color of the rubber. The rubber should appear new or deeper in color. To prime this surface, apply a coat of Devcon® FL-20 Primer and allow to dry tackfree for 15-20 minutes. Use Devcon®FL-40 Primer on "hard-to-bond" rubber surfaces as this gives ultimate peel resistance. Multiple coats may be necessary for porous rubber surfaces.

For MAXIMUM ADHESION, sandblast the surface with an angular abrasive until a minimum depth profile of 2-3 mils is met. Blast to near-white finish specification SSPC-SP5 (Steel Structure Painting Council). Prime surface immediately after sandblasting to prevent oxidation.

Mixing Instructions:

To ensure proper cure speeds and hardness, mix Flexane at a temperature between 65°F-85°F (18°C to 29°C)

FOR 1 LB. UNITS

- 1.Add hardener to resin.
- 2.Vigorously mix with screwdriver or spatula for two minutes, while continuously scraping material away from sides and bottom of container. NOTE: Flexane putties will thicken rapidly during these first two minutes of mixing, but this DOES NOT mean that the polymer is curing.
- 3. Transfer the mixed material to the plastic container (included in kit).
- 4. Wipe spatula clean, and stir again for two more minutes.
- 5. Continue to mix until a uniform, streak-free consistency is obtained.

FOR 4 LB. UNITS:

Use a propeller-type Jiffy Mixer Model ES on an electric drill.

Mix until color is uniform and consistent (approx. 4-6 min.), while continuously scraping material away from sides and bottom of container.

NOTE: Completely submerge propeller, otherwise large amounts of air will be added resulting in air bubbles on the finished product's surface.

FOR 400 ml cartgs.

Application

1. Mount cartridge onto manual gun (#15043) or pneumatic gun (#15041).

Standard Tests

Cure Shrinkage ASTM D 2566
Tear Resistance ASTM D 624
Maximum Elongation ASTM D 412
Dielectric Strength, volts/mil ASTM D 149
Cured Hardness Shore D ASTM D 2240
Tensile Strength (Urethanes) ASTM D 412

Instructions:

- 2. Attach #15047 mix nozzle (used with both cartridges).
- 3. Clip mix nozzle back to desired orifice size.
- 4. Squeeze cartridge, allowing first THREE INCHES of material to discharge until a unified mix is exuding from nozzle (color is uniform with no striations).
- 5. Finish application as quickly as possible.

Replace mix nozzle every four minutes to ensure complete mix, with no soft spots. Because of the short pot life (8 minutes), stopping between uses can result in Flexane product curing IN the mix nozzle. Further mixing will be off ratio.

Storage:

Store at room temperature, 70 °F (21°C)

Compliances:

None

Chemical Resistance:

Chemical resistance is ca	lculated with a 7	day, room temp. cure (30 days immersion) @ 75°F (24°C)
1,1,1-Trichloroethane	Poor	Phosphoric 10%	Very good
Aluminum Sulfate 10%	Very good	Potassium Hydroxide 40%	Very good
Cutting Oil	Fair	Sodium Hydroxide 50%	Very good
Gasoline (Unleaded)	Poor	Sodium Hypochlorite	Very good
Hydrochloric 10%	Very good	Xylene	Poor
Hydrochloric 36%	Very good	1	
Isopropyl	Poor	1	
Methyl Ethyl Ketone	Poor	1	

.p. care (ee aayee.e.e.)				
		Very good		
	Potassium Hydroxide 40%	Very good		
	Sodium Hydroxide 50%	Very good		
	Sodium Hypochlorite	Very good		
	Xylene	Poor		

Precautions:

FOR INDUSTRIAL USE ONLY: Please refer to the appropriate <u>Safety Data Sheet prior</u> to using this product.

Warrantv:

ITW Performance Polymers will replace any material found to be defective. Because the storage, handling and application of this material is beyond our control, we can accept no liability for the results obtained.

Order Information:

Item No. Package Size 15049 400 ml cartg.

Contacts:

www.itwpp.com

ITW Performance Polymers (EMEA) ITW Performance Polymers (US)

Bay 150, Shannon Industrial Estate 30 Endicott Street Shannon, County Clare, Ireland V14 DF82 Danvers, MA 01923 USA TEL: +353 61 771 500 TEL: 855 489 7262

FAX: +353 61 471 285 FAX: 978 774 0516 Email: customerservice.shannon@itwpp.com Email: info@itwpp.com

Disclaimer:

Product Use: The information herein is based upon good faith testing that ITW PP believes are reliable, but the accuracy or completeness of such information is not guaranteed. Many factors beyond ITW PP control and uniquely within user's knowledge and control can affect the use and performance of an ITW PP product in a particular application. Given the variety of influencers on performance, the data here is not intended to substitute end user testing. It is the end users sole responsible for evaluating any ITW PP product and determining whether it is fit for a particular purpose and suitable for user's design, production, and final application.

Exclusion of Warranties: As to the herein described materials and test results, there are no warranties which extend beyond the description on the face hereof. ITW PP makes no other warranties, express or implied, including, but not limited to, any implied warranty of merchantability or fitness for a particular purpose. Since the use of the herein described involves many variables in methods of application, design, handling and/or use, the user, in accepting and using these materials, assumes all responsibility for the end result. ITW PP shall not otherwise be liable for loss of damages, whether direct, indirect, special, incidental, or consequential, regardless of the legal theory asserted, including negligence, warranty, or strict liability.