Standard Tests

Adhesive Tensile Shear ASTM D 1002

Coef. of Thermal Expansion ASTM D 696

Compressive Strength ASTM D 695 Cured Hardness Shore D ASTM D 2240

Cure Shrinkage ASTM D 2566

Flexural Strength ASTM D 790

Dielectric Constant ASTM D 150



Wear Guard™ High Impact

Description:

High density, micro alumina ceramic bead-filled epoxy system with urethane acyrlate for superior impact abrasion used for protecting equipment against tremendous impact and flex.

Intended Use:

High impact applications in pumps, scrubbers, screens, chutes, handling equipment and screw conveyers.

Features:

Extremely wear resistant Non-sagging putty, creamy paste High compression and impact strength Service temperatures to 300°F (149°C)

Limitations:

None.

Typical Physical Properties: Technical data should be considered representative or typical only and should not be used for specification purposes.

Cured 7 Days @ 75°F (24°C)

Adhesive Tensile Shear
Coefficient of Thermal Expansion (x10-6)
Compressive Strength
Cured Shrinkage
Dielectric Constant
Flexural Strength
Hardness
Solids by Volume

Tensile Strength
Uncured Properties @ 72°F (23°C)

Temperature Resistance

Color
Coverage (1/4" / 6.35 mm)
Full Cure
Functional Cure
Mix Ratio by Volume
Mix Ratio by Weight
Mixed Viscosity

Recoat Time Specific Gravity Specific Volume

Pot Life @ 75F

Typical Values

2,567 psi (17.7 MPa) 34 in/in.°F (61.2 cm/cm.°C) 7,250 psi (50 MPa) 0.0006 in/in (cm/cm) 46 6,144 psi (42 MPa) 85 Shore D

100 Wet: 140°F (60°C); Dry: 300°F (149°C)

4,220 psi (29 MPa)

4,220 psi (2

Dark Grey

50 in²/lb (711 cm²/Kg)

16 hrs. 6 - 8 hrs. 2.5 : 1 2.5 : 1 Non-sag putty 30 min. 4 - 6 hrs.

18.6 lb/Gal (2.23 g/cm³) 12.4 in³/lb (0.448 cm³/g)

Surface Preparation:

- 1. Thoroughly clean the surface with Devcon® Cleaner Blend 300 to remove all oil, grease and dirt.
- 2. Grit blast surface area with 8-40 mesh grit, or grind with a coarse wheel or abrasive disc pad, to create increased surface area for better adhesion (Caution: An abrasive disc pad can only be used provided white metal is revealed). Desired profile is 3-5mil, including defined edges (do not "feather-edge" epoxy).

Note: For metals exposed to sea water or other salt solution, grit-blast and high-pressure-water-blast the area, then leave overnight to allow any salts in the metal to "sweat" to the surface. Repeat blasting to "sweat out" all soluble salts. Perform chloride contamination test to determine soluble salt content (should be no more than 40 ppm).

- 3. Clean surface again with Devcon® Cleaner Blend 300 to remove all traces of oil, grease, dust or other foreign substances from the grit blasting.
- 4. Repair surface as soon as possible to eliminate any changes or surface contaminants.

WORKING CONDITIONS: Ideal application temperature is 55°F to 90°F (13°C - 32°C). In cold working conditions, directly heat repair area to 100-110°F (38°C - 43°C) prior to applying epoxy and maintain at this temperature during product cure to dry off any moisture contamination or solvents, as well as to achieve maximum performance properties.

Mixing Instructions:

- ---- It is strongly recommended that full units be mixed, as ratios are pre-measured. ----
- 1. Add hardener to resin.
- 2. Mix thoroughly with screwdriver or similar tool (continuously scrape material away from sides and bottom of container) until a uniform, streak-free consistency is obtained.

INTERMEDIATE SIZES (1,2,3 lb. units): Place resin and hardener on a flat, disposable surface such as cardboard, plywood or plastic sheet. Use a trowel or wide-blade tool to mix the material as in Step 2 above.

LARGE SIZES: (25 lb., 30 lb., 50 lb, buckets); Use a T-shaped mixing paddle or a propeller-type Jiffy Mixer Model ES

on an electric drill. Thoroughly fold putty by vigorously moving paddle/propeller up and down until a homogenous mix of resin and hardener is attained.

Application Instructions: ADDITIONAL SURFACE PREPARATION INFORMATION:

If grit blasting is not possible, and expandable metal cannot be used, apply Devcon Brushable Ceramic at 11-18 mils to prime the metal surface. Allow to cure for approximately 2 hours, or until a fingernail can almost depress the primed surface. Immediately apply Wear Guard™ High Impact to the surface. DO NOT let the "prime coat" fully cure before applying WG High Impact.

Spread mixed material on repair area at a minimum thickness of 1/4" (6.4 mm). Work firmly into substrate to ensure maximum surface contact. Wear Guard™ High Impact fully cures in 16 hours, at which time it can be machined, drilled, or painted.

FOR BRIDGING LARGE GAPS OR HOLES

Place fiberglass sheet, expanded metal, or mechanical fasteners between repair area and Wear Guard™ High Impact prior to application.

FOR VERTICAL SURFACE APPLICATIONS

Wear Guard™ High Impact can be troweled up to 3/4" thick without sagging.

FOR MAXIMUM PHYSICAL PROPERTIES

Cure at room temperature for 2.5 hours, then heat cure for 4 hours at 200°F (93°C)

FOR ± 70°F (21°C) APPLICATIONS

Applying epoxy at temperatures below 70°F (21°C) lengthens functional cure and pot life times. Conversely, applying above 70°F (21°C) shortens functional cure and pot life.

Storage:

Store at room temperature, 70°F (21°C)

Compliances:

None

Chemical Resistance:

Chemical resistance is calculated with a 7 day, room temp. cure (30 days immersion) @ 75°F (24°C)

1,1,1-Trichloroethane	Very good
Ammonia	Excellent
Benzene	Very good
Gasoline	Excellent
Hydrochloric 10%	Very good
Methanol	Poor
Methyl Ethyl Ketone	Poor
Methylene Chloride	Poor

Nitric 10%	Fair
Phosphoric 10%	Fair
Potassium Hydroxide 40%	Excellent
Sodium Hydroxide 50%	Excellent
Sulfuric 10%	Very good
Toluene	Excellent
Trisodium Phosphate	Very good

Precautions:

FOR INDUSTRIAL USE ONLY: Please refer to the appropriate <u>Safety Data Sheet prior to using this product.</u>

Warranty:

ITW Performance Polymers will replace any material found to be defective. Because the storage, handling and application of this material is beyond our control, we can accept no liability for the results obtained.

Order Information:

<u>Item No.</u> <u>Package Size</u> 11460 30 lb. (13.6 kg)

Contacts:

www.itwpp.com

ITW Performance Polymers (EMEA)

Bay 150, Shannon Industrial Estate
Shannon, County Clare, Ireland V14 DF82

ITW Performance Polymers (US)
30 Endicott Street
Danvers, MA 01923 USA

TEL: +353 61 771 500 TEL: 855 489 7262
FAX: +353 61 471 285 FAX: 978 774 0516
Email: customerservice.shannon@itwpp.com Email: info@itwpp.com

Disclaimer:

Product Use: The information herein is based upon good faith testing that ITW PP believes are reliable, but the accuracy or completeness of such information is not guaranteed. Many factors beyond ITW PP control and uniquely within user's knowledge and control can affect the use and performance of an ITW PP product in a particular application. Given the variety of influencers on performance, the data here is not intended to substitute end user testing. It is the end users sole responsible for evaluating any ITW PP product and determining whether it is fit for a particular purpose and suitable for user's design, production, and final application.

Exclusion of Warranties: As to the herein described materials and test results, there are no warranties which extend beyond the description on the face hereof. ITW PP makes no other warranties, express or implied, including, but not limited to, any implied warranty of merchantability or fitness for a particular purpose. Since the use of the herein described involves many variables in methods of application, design, handling and/or use, the user, in accepting and using these materials, assumes all responsibility for the end result. ITW PP shall not otherwise be liable for loss of damages, whether direct, indirect, special, incidental, or consequential, regardless of the legal theory asserted, including negligence, warranty, or strict liability.