

## **Wet Surface Repair Putty (UW)**

Description:

Makes (effective) repairs to metal, concrete, wood surfaces in wet and dry environments.

Intended Use:

Industrial Use: Repairing and refitting pipes, valves, pumps, and tanks. Repair concrete vessels and piping in wet

environments. This product will bond to a wet or damp surface.

Features:

Bonds to aluminum, concrete, and many other metals

Bonds to ferrous and non-ferrous metals

Non-rusting

Bonds to wet surfaces, patches, and seals metals

Non-sagging

Limitations:

Suitability of product is determined by the end user for their application and process.

Typical Physical Properties: Technical data should be considered representative or typical only and should not be used for specification purposes.

## Cured 7 Days @ 75°F (24°C)

Adhesive Tensile Shear Coefficient of Thermal Expansion (x10-6) Compressive Strength Cured Shrinkage Dielectric Constant Dielectric Strength Flexural Strength Hardness

Modulus of Elasticity Solids by Volume

Temperature Resistance

#### **Typical Values**

2,685 psi (18.5 MPa) 18 in/in.°F (32.4 cm/cm.°C) 5,625 psi (38.8 MPa) 0.0020 in/in (cm/cm)

150 volts/mil (5.9 kV/mm) 4,990 psi (34.4 MPa) 82 Shore D

7.5 psi x10<sup>5</sup> (5.2 GPa)

Wet: 120°F (49°C); Dry: 250°F (121°C)

## **Standard Tests**

Adhesive Tensile Shear ASTM D 1002 Cure Shrinkage ASTM D 2566 Coef. of Thermal Expansion ASTM D 696 Compressive Strength ASTM D 695 Cured Hardness Shore D ASTM D 2240 Dielectric Strength, volts/mil ASTM D 149 Dielectric Constant ASTM D 150

Flexural Strength ASTM D 790 Modulus of Elasticity ASTM D 638 Thermal Conductivity ASTM C 177

#### Uncured Properties @ 72°F (23°C)

Color

Grey Coverage (1/4" / 6.35mm) 68 in2/lb (967 cm2/Kg)

**Functional Cure** 24 hours Mix Ratio by Volume 1:1 Mix Ratio by Weight 1.4:1 Mixed Viscosity Puttv Pot Life @ 75°F (24°C) 45 min. Recoat Time 10-12 hours

Specific Gravity 11.7 lb/Gal (1.4 g/cm3) Volume 17 in3/lb (0.61 cm3/g)

### Surface Preparation:

- 1. Thoroughly clean the surface with Devcon® Cleaner Blend 300 to remove all oil, grease and dirt.
- 2. Grit blast surface area with 8-40 mesh grit, or grind with a coarse wheel or abrasive disc pad, to create increased surface area for better adhesion (Caution: An abrasive disc pad can only be used provided white metal is revealed). Desired profile is 3-5mil, including defined edges (do not "feather-edge" epoxy).

Note: For metals exposed to sea water or other salt solution, grit-blast and high-pressure-water-blast the area, then leave overnight to allow any salts in the metal to "sweat" to the surface. Repeat blasting to "sweat out" all soluble salts. Perform chloride contamination test to determine soluble salt content (should be no more than 40ppm).

- 3. Clean surface again with Devcon® Cleaner Blend 300 to remove all traces of oil, grease, dust or other foreign substances from the grit blasting.
- 4. Repair surface as soon as possible to eliminate any changes or surface contaminants.

WORKING CONDITIONS: Ideal application temperature is 55 - 90°F (13 - 32°C). In cold working conditions, directly heat repair area to 100 - 110°F (38 - 43°C) prior to applying epoxy and maintain at this temperature during product cure to dry off any moisture, contamination or solvents, as well as to achieve maximum performance properties.

#### Mixing Instructions:

- ---- It is strongly recommended that full units be mixed, as ratios are pre-measured. ----
- 1. Add hardener to resin.
- 2. Mix thoroughly with screwdriver or similar tool (continuously scrape material away from sides and bottom of container) until a uniform, streak-free consistency is obtained.

INTERMEDIATE SIZES (1,2,3 lb. units): Place resin and hardener on a flat, disposable surface such as cardboard, plywood or plastic sheet. Use a trowel or wide-blade tool to mix the material as in Step 2 above.

LARGE SIZES: (25 lb., 30 lb., 50 lb. buckets): Use a T-shaped mixing paddle or a propeller-type Jiffy Mixer Model ES on an electric drill. Thoroughly fold putty by vigorously moving paddle/propeller up and down until a homogenous mix of resin and hardener is attained.

# Application Instructions:

Spread mixed material on repair area and work firmly into substrate to ensure maximum surface contact. Underwater Repair Putty fully cures in 24 hours, at which time it can be machined, drilled, or painted

#### FOR MAXIMUM PHYSICAL PROPERTIES

Cure at room temperature for 2.5 hours, then heat cure for 4 hours @ 200°F.

#### FOR ± 70°F (21°C) APPLICATIONS

Applying epoxy at temperatures below 70°F (21°C) lengthens functional cure and pot life times. Conversely, applying above 70°F shortens functional cure and pot life.

For Underwater or submerged repairs consider the following:

- Remove all dirt, barnacles, flaking paint, and algae/seaweed from the substrate.
- Wipe area with a clean cloth to remove any film on the surface. Obviously, you cannot degrease underwater, but wiping and turning a clean cloth often will remove any film on the surface.
- Abrade the surface if possible. (Use mechanical means or a file to accomplish.)
- The oxidation can be removed by mechanical means, such as water, grit-blasting, or by chemical means.
- Make the repair as soon as possible to avoid surface contamination.

Storage:

Shelf life 3 yrs from manufacture. See package label. Store at room temperature, 70 °F (21°C)

Compliances:

None

Chemical Resistance:

Chemical resistance is calculated with a 7 day, room temp. cure (30 days immersion) @ 75°F (24°C)

Ammonia	Very good
Chlorinated Solvent	Poor
Hydrochloric 10%	Fair
Kerosene	Very good
Methanol	Poor
Sodium Hydroxide 10%	Very good
Sulfuric 10%	Fair
Toluene	Very good

Precautions:

 $\textbf{FOR INDUSTRIAL USE ONLY:} \ Please \ refer \ to \ the \ appropriate \ \underline{\underline{\textbf{S}}} a fety \ \underline{\underline{\textbf{D}}} a ta \ \underline{\underline{\textbf{S}}} heet \ prior \ to \ using \ this \ product.$ 

Warranty:

ITW Performance Polymers will replace any material found to be defective. Because the storage, handling and application of this material is beyond our control, we can accept no liability for the results obtained.

Order Information:

Contacts:

www.itwpp.com

ITW Performance Polymers (EMEA)ITW Performance Polymers (US)Bay 150, Shannon Industrial Estate30 Endicott StreetShannon, County Clare, Ireland V14 DF82Danvers, MA 01923 USA

TEL: +353 61 771 500 TEL: 855 489 7262
FAX: +353 61 471 285 FAX: 978 774 0516
Email: customerservice.shannon@itwpp.com Email: info@itwpp.com

Disclaimer:

**Product Use**: The information herein is based upon good faith testing that ITW PP believes are reliable, but the accuracy or completeness of such information is not guaranteed. Many factors beyond ITW PP control and uniquely within user's knowledge and control can affect the use and performance of an ITW PP product in a particular application. Given the variety of influencers on performance, the data here is not intended to substitute end user testing. It is the end users sole responsible for evaluating any ITW PP product and determining whether it is fit for a particular purpose and suitable for user's design, production, and final application.

**Exclusion of Warranties**: As to the herein described materials and test results, there are no warranties which extend beyond the description on the face hereof. ITW PP makes no other warranties, express or implied, including, but not limited to, any implied warranty of merchantability or fitness for a particular purpose. Since the use of the herein described involves many variables in methods of application, design, handling and/or use, the user, in accepting and using these materials, assumes all responsibility for the end result. ITW PP shall not otherwise be liable for loss of damages, whether direct, indirect, special, incidental, or consequential, regardless of the legal theory asserted, including negligence, warranty, or strict liability.